

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 05/13/2010
Monitor Time: 2/20/2011 12:19

Serial Number: 65126069
CF: 2.21

Inspection Company

Dave Reynolds
ISHI-MWIAQ-MB RADON
Urbandale, Iowa-50323
Phone Number: 515-783-4669
License Number: S00264

Billing Information

Site Information

Site & Condition

Wind:
Year Built:
Mitigation System: Not Installed
SqFt:

Atmospheric Condition:
Structure Type:
Monitor Location:

Test Summary

Start Time: 02/18/2011 11:11
End Time: 02/20/2011 11:11
Measurement Interval(hr): 1.0
Exposure Time: 2 Days 0 hrs

Overall Avg: 6.8 pCi/l
EPA Avg: 6.7 pCi/l

